

From glowbugs@theporch.com Sat Jun 15 14:28:31 1996
Return-Path: glowbugs@theporch.com
Received: from uro (localhost.theporch.com [127.0.0.1]) by uro.theporch.com
(8.7.5/AUX-3.1.1) with SMTP id OAA22846; Sat, 15 Jun 1996 14:26:05 -0500 (CDT)
Date: Sat, 15 Jun 1996 14:26:05 -0500 (CDT)
Message-Id: <199606151926.OAA22846@uro.theporch.com>
Errors-To: ws4s@midtenn.net
Reply-To: glowbugs@theporch.com
Originator: glowbugs@theporch.com
Sender: glowbugs@theporch.com
Precedence: bulk
From: glowbugs@theporch.com
To: Multiple recipients of list <glowbugs@theporch.com>
Subject: GLOWBUGS digest 215
X-Listprocessor-Version: 6.0c -- ListProcessor by Anastasios Kotsikonas
X-Comment: Please send list server requests to listproc@theporch.com
Status: 0

GLOWBUGS Digest 215

Topics covered in this issue include:

- 1) Regen question
by herr@ridgecrest.ca.us (Michael Herr)

Date: Fri, 14 Jun 1996 22:15:14 -0700
From: herr@ridgecrest.ca.us (Michael Herr)
To: glowbugs@theporch.com
Subject: Regen question
Message-ID: <v01530502ade8e62efdd8@[199.120.150.134]>

Gang,

I have an old Heathkit GR-81 reg receiver. I built it in my pre Novice days back in the 60's (after picking prunes all summer...but that's another story) and have been kicking it around for a long time. Anyway, I wrote a while back about breaking it out and rekindling a lost love. Well, after much listening, the old tube rig just doesn't seem as sensitive as it should be , or as I remember. Been thinking about replacing the tubes as they are the originals, also need to look at the caps inside. Any thoughts?

73

Mike WA6ARA

End of GLOWBUGS Digest 215
